

Ref: Sugar Plant—Repair Gearbox for screw press

Type: PB22FS—20 Ton!

8 shafts—18 bearings



RCA: Bearing damage low speed shaft

Other projects

